

Mobile: 0414 567 473

jodie@propertyreportsperth.com.au

# Routine Inspection Report

Date: 1st February 2023

**Owner Name:** 

#### **Property Details**

**Address** Sample Routine Inspection Report

**Inspected By** Property Reports Perth

I write to advise that a visual Routine Inspection was conducted at your property.

Please refer to this inspection for any important notes or maintenance issues.

If you have any questions in relation to the Routine Inspection Report, please do not hesitate to contact me at <a href="mailto:jodie@propertyreportsperth.com.au">jodie@propertyreportsperth.com.au</a>.

#### Regards

Jodie Sallie
Property Reports Perth

### **Maintenance Required**

The pool fence gate latch is loose.

### **Suggested Improvements**

Repaint front balcony ceiling as the paint is heavily weathered and peeling. Repair cracks to alfresco ceiling. Decking is heavily weathered and worn.

#### **Our Summary**

Overall the tenants presented the property generally tidy inside. Cleaning required as noted in the report. Weeds to driveway need to be sprayed/removed. Photos have been taken and a link for the photos will be emailed separately.



Mobile: 0414 567 473

jodie@propertyreportsperth.com.au

## **Observations from this Inspection**

Area	Comments/Notes
Front of Property	Lawn is a little patchy, mostly green and healthy. There are a lot of weeds to the top section of the lawn by the house.
	Gardens have minor weeds, plants are healthy. The rendered garden bed wall is weathered and rusting to the edges.
	Many weeds to the driveway.
Garage	Garage door all appears to be intact and in good condition.
	Light in working order.
	Unable to view floor due to the tenant's belongings.
Entry	Front doors have a lot of marks. Locks intact.
	Light fittings are intact and globes are in working order.
	Walls appear in good overall condition.
	Floor is clean.
Study off the entry	Used as a spare bedroom.
	Brown painted wall has many chips. The other walls appear in good overall condition.
	Carpet is clean with no obvious signs of staining.
	Window glass intact. Blinds are secure and intact.
	Light intact and in working order.
Downstairs	Walls have washable marks.
bedroom	Light intact and in working order.
	Carpet is clean with no obvious signs of staining.
	Window glass intact. Blinds are secure and intact.
	Robe doors are secure and intact.
	Room is tidy.
Bathroom	Walls appear in good overall condition.
downstairs	Light intact and in working order.
	Floor is in good, clean condition.
	Window glass is intact.
	Mirror is clean and intact.
	Basin and surfaces wiped clean.
	Shower screen is clean and intact. Tiles and grout are clean.
	Toilet is clean, no apparent leaks.



Mobile: 0414 567 473

jodie@propertyreportsperth.com.au

odie@propertyreportspertif.com.au		
	Exhaust fan cover is slighlty dusty.	
	Taps and fittings are intact with no apparent leaks.	
Stairs	Minor marks to the walls, many chips to the bottom of the walls.	
	Light fitting intact and in working order.	
	Window glass is intact.	
<b>Upstairs lounge</b>	Glass to the door and windows intact. Blinds secure and intact.	
	Lights intact and in working order.	
	Walls have a lot of marks, chips to the lower floor line.	
	Generally presents neat and tidy.	
Balcony	Metal posts are weathered and rusting.	
	Paint peeling to the ceiling.	
	Railing is secure and intact.	
	Floor tiles need cleaning.	
	Light is rusting, working order.	
Bedroom 1	Walls have minor marks visible, chips to the lower floor line.	
	Lights intact and in working order.	
	Carpet clean, no obvious signs of staining. Slightly rippling. Fraying by the ensuite.	
	Glass door intact, needs cleaning. Window glass intact.	
	The bedroom generally presents neat and tidy.	
<b>Ensuite and toilet</b>	Walls appear in good overall condition.	
	Cracking under the cornices.	
	Light intact and in working order.	
	Floor is in good, clean condition.	
	Window glass is intact.	
	Mirrors are clean and intact.	
	Basins and surfaces wiped clean.	
	Shower screen is intact, water marked. Tiles and grout are clean.	
	Toilet has build up to the base, no apparent leaks.	
	Exhaust fan covers are slighlty dusty.	
	Taps and fittings are intact with no apparent leaks.	
Upstairs hallway	Walls have minor marks, chips to the lower floor line.	
	Light is in working order.	
	Carpet is clean, no obvious signs of staining.	
Bedroom 2	Walls have minor marks, chips to the lower floor line.	
	Light is in working order.	
	Carpet is clean, no obvious signs of staining.	
	Window glass intact, blinds secure and intact.	



Mobile: 0414 567 473

jodie@propertyreportsperth.com.au

	e marks. rder. bybvious signs of staining. , blinds secure and intact. and intact. arks. rder.
Light is in working of Carpet is clean, no of Window glass intact Robe doors secure at Walls have minor managed by Light is in working of the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean, no of Window glass intact Robe doors secure at the Carpet is clean with the Carpet is cle	rder. byvious signs of staining. , blinds secure and intact. and intact. arks. rder.
Carpet is clean, no of Window glass intact Robe doors secure a Walls have minor managed Light is in working of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of Window glass intact Robe doors secure a warm of the Carpet is clean, no of the Carpet i	obvious signs of staining.  , blinds secure and intact.  and intact.  arks.  rder.
Window glass intact Robe doors secure a  Walls have minor m Light is in working o	, blinds secure and intact. and intact. arks. rder.
Robe doors secure a  Walls have minor ma  Light is in working o	arks. rder.
Bedroom 4 Walls have minor ma Light is in working o	arks. rder.
Light is in working o	rder.
Carpet is clean, no c	1
	obvious signs of staining.
Window glass intact	, blinds secure and intact.
Robe doors secure a	and intact. Stickers to one robe door.
<b>Upstairs bathroom</b> Walls have some mi	nor marks.
Light/heater globes	/fan intact and in working order.
Floor is in good, clea	an condition.
Window glass is inta	ct.
Mirror is clean and i	ntact.
Basin and surfaces v	viped clean.
Shower screen is cle	an and intact. Tiles and grout are clean.
Taps and fittings are	e intact with no apparent leaks.
<b>Upstairs toilet</b> Walls have minor m	arks.
Light is in working o	rder.
Exhaust fan cover is	damage, needs cleaning.
Floor is clean.	
Toilet needs cleanir	g, no apparent leaks.
<b>Laundry</b> Walls have minor managed	arks.
Floor needs vacuum	ing.
Glass door intact, no	eeds cleaning. Flyscreen door wire is heavily torn and damage.
Trough is clean.	
Taps and fittings are	e intact with no apparent leaks.
Linen doors are secu	ure and intact.
<b>Theatre room</b> There are a lot of ch	ips to the brown painted walls. The rest of the walls have minor
marks visible.	
Window glass intact	. Blind secure and intact.
Carpet is clean, no c	bvious signs of staining. Threads pulled by the family/meals floor.
Lights are in working	g order.
Room generally tidy	
<b>Kitchen</b> Sink needs a wipe o	ver.



Mobile: 0414 567 473

jodie@propertyreportsperth.com.au

Jodie@propertyreportspertif.com.au		
	Floor is clean.	
	Oven needs cleaning.	
	Hotplates are clean.	
	Rangehood needs cleaning. Light in working order.	
	There are a lot of chips to the pantry door and frame.	
Family/meals	Windows and glass doors intact. Blinds secure and intact.	
	Floor is clean.	
	Ceiling has water damage/staining to the back.	
	Lights are in working order.	
	Area is a little cluttered and untidy.	
Rear of property	Cracks to the alfresco ceiling.	
	Decking is heavily weathered and worn.	
	Glass pool fencing is intact, the latch to the door is loose and needs to be attended to.	
	The wooden storage boxes in the pool area are weathered and wood is bowed.	
	One dead palm tree in the pool area. The tenants are in the process of cleaning up the	
	gardens are removing dead leaves etc and there is a pile of garden debris on the lawn	
	that they will be taking to the tip.	
	Majority of the lawn is green and healthy.	
	There are weeds to the side of the house.	

#### Disclaimer:

Property Reports Perth are not qualified to assess the structural aspects of areas, including but not limited to staircases, decking and balconies, or to ensure that plumbing, electrical or gas fixtures or fittings, glass windows, doors and balustrades, smoke alarms, pests (ie. termites), asbestos, swimming pool safety barriers (and associated fittings) comply and operate in accordance with applicable building/council codes and/or laws and regulations. Property Reports Perth recommend that landlords have regular inspections carried out by suitable qualified licensed and insured contractors and experts in the appropriate area when necessary.